

**City of Dallas**  
**OFFICE MEMORANDUM**

To- File

3 September 1954

Subject: Red River Run-Off

Photographs taken 17 February 1954.

First photograph was taken of pump station. The second photograph was taken of the outlet from 48-inch line at Starks ranch showing the erosion of the ditch which was built by the contractor. Third photograph was taken at the bridge forming the south boundary line of Starks ranch. Fifth photograph was taken on the English place on his south crossing to be compared with previous photographs. Sixth photograph was taken at the south crossing facing north showing the high water line on the ditch. It appears from the water lines that about 2½ feet of water flow over the crossing when pumping at 79 million gallons a day. The seventh photograph was taken of his north crossing --that is, the seventh and eighth photographs were made of two crossings on the north end of his property.

Henry Graeser

HG:AW